


Site Photographs

Exide
Los Angeles Recycling Facility
Los Angeles County, California

Photograph date: 2/16/2011




Photograph 1 – View facing southwest at drainage channel that serves as the western border of the northern portion of the Facility.



Photograph 2 – View facing southwest at drainage channel that bisects the southern portion of the Facility.



Photograph 3 – Series of four storm water settling tanks (approximately 10,000 gallons each) that are used to feed storm water into the WWTP.



Photograph 4 – A pumping station located near the northeast corner of the storm water retention pond.

Site Photographs

Exide
Los Angeles Recycling Facility
Los Angeles County, California

Photograph date: 2/16/2011



Photograph 5 – View of batteries being placed in the battery dump bin from the battery recycling delivery dock.



Photograph 6 – View of battery dump bin from the battery recycling delivery dock.



Photograph 7 – View facing north at equipment and pavement washing activity outside the blast furnace feed room.



Photograph 8 – Close-up view of washing activity facing northwest.


Site Photographs

Exide
Los Angeles Recycling Facility
Los Angeles County, California


Photograph date: 2/16/2011




Photograph 9 – View of wash water (shown in Photograph 8) flowing through a scrap iron stockpile, facing east.



Photograph 10 – View toward the railway exit along South Indiana Street, facing southeast.



Photograph 11 – Close-up view of accumulated wash water along the tracks, facing southeast.



Photograph 12 – View of wash water flowing into the trench drain adjacent to the railway exit, facing southeast.


Site Photographs

Exide
Los Angeles Recycling Facility
Los Angeles County, California

Photograph date: 2/16/2011



Photograph 13 – View of wash water flowing into the trench drain adjacent to the railway exit, facing southwest.



Photograph 14 – View of concrete curb from inside the North Yard, facing northwest.



Photograph 15 – View of concrete curb from bridge over the drainage channel in the North Yard, facing north.



Photograph 16 – View of crack present in the concrete curb adjacent to the battery recycling loading dock, facing west.

Site Photographs

Exide
Los Angeles Recycling Facility
Los Angeles County, California

Photograph date: 2/16/2011



Photograph 17 – Close-up view of crack shown in Photograph 16.



Photograph 18 – View of another crack present in the concrete curb to the north of Photograph 17, facing northwest.



Photograph 19 – View from the west side of the RMPS building facing northeast. Note truck traffic exiting the Facility.



Photograph 20 – View of 26th Street entrance/exit, facing southeast. Note presence of truck tracks and standing water.

Site Photographs

Exide
Los Angeles Recycling Facility
Los Angeles County, California

Photograph date: 2/16/2011



Photograph 21 – View of 26th Street entrance/exit, facing east. Note truck tracks and storm water leading from the Facility.



Photograph 22 – View of 26th Street entrance/exit, facing east. Note truck tracks and storm water leading from the Facility.



Photograph 23 – Mobile equipment wash rack located to the west of the Mobile Equipment Maintenance Garage, facing south.




Photograph 24 – Close-up view of mobile equipment wash rack shown in Photograph 23.

Site Photographs	Exide Los Angeles Recycling Facility Los Angeles County, California	Photograph date: 2/16/2011
-------------------------	---	----------------------------



Photograph 25 – Vehicle wheel wash facility northeast of the Bandini Boulevard entrance/exit, facing west.



Photograph 26 – Close-up view of vehicle wheel wash facility shown in Photograph 25.